

THIS IS A TECH REPORT FOR MISSION C174C. THE DRIVER DID NOT TURN ON SYSTEM SIX UNTIL 02302. APPROXIMATELY THIRTY SECONDS LATER HE SWITCHED ANTENNAS TO BOTH SIDES. ANTENNA SWITCHING WAS SUPPOSED TO OCCUR AT 0111Z. SWITCH WAS THROWN AT 0229.302. THE ONLY SIGNALS COLLECTED FROM TAKE OFF TO ABOVE TIMES WILL BE FROM SYSTEM TWELVE. THE CAPSIAN DRIVE MOTOR ON SLAVE RECORDER WAS RUNNING VERY ERRATIC.

END OF MESSAGE

GROUP 1 Encluded from unterration also managed in and declaration in

